

INSPECTOR NOTE

Building:	
Street:	19 Cnr. Kapteijn Street & Twist Street
Suburb:	Hillbrow
Postal Code:	
Date:	2023-08-28
Time:	55:00
Inspector:	GODFREY MNGUNI
Type:	GENERAL
Follow-Up Date:	
Comments:	No one was still occupying the building due to flood risk and structural integrity caused by overflowing sewage system according to Nkosinathi Moyo of the GS investigations. All the chickens were cleared out as the basement was overflowing with waste water. No info on the new address of operation. Case finalized until new leads.