

INSPECTOR NOTE

Building:

Street:

Suburb:

Postal Code:

Date:

Time:

Inspector:

UNIT2

506 SANDTON SLAY

MORNINGSIDE

2024-04-30

12:27

RONALDM RAMALATA

Type:

Follow-Up Date:

Comments:

Captured By:

POST-HOME INSPECTION NOTE

post home inspection passed

CILIA MALAHLELA 2024-05-02 12:01