

INSPECTOR NOTE

Building:	
Street:	114 HILTON ROAD
Suburb:	LINBRO PARK
Postal Code:	
Date:	2024-11-21
Time:	14:57
Inspector:	RONALDM RAMALATA
Type:	CALL RECORD - MADE
Follow-Up Date:	2024-11-25
Comments:	A follow up inspection will be conducted on Monday.
Captured By:	Ronald Ramalata 2024-11-21 14:57