

INSPECTOR NOTE

Building:	
Street:	34 CORNER REID & VISAGIE STREET
Suburb:	SUNDRA
Postal Code:	
Date:	2025-04-03
Time:	15:29
Inspector:	CHARNE HAND

Type:	CASE DISCUSSION NOTE
Follow-Up Date:	
Comments:	Contact was made with Mr Nkhensani Khosa, the Air and Quality and Environmental Officer who has been overseeing inspections at the feedlot since November 2024. Ms. Khosa provided valuable information regarding the case history, the nature of the initial complaint, and the progress of the inspections conducted thus far. Mr Khosa explained that the case had been reported following an incident in November 2024, when a blockage in the municipal drain caused contaminated water to flood into the street. The Department of Environmental Management had subsequently conducted investigations, determining that the municipality was responsible for unblocking the drain. Furthermore, Mr Khosa detailed the sequence of inspections that had been carried out since the initial report. Each inspection had addressed various aspects of the feedlot's operations, focusing on environmental management, infrastructure improvements, and compliance with regulations. In response to the inquiry, Mr Khosa advised that I formally request the case history documents from the Department via email. These documents would provide a comprehensive record of all inspections, reports, and any follow-up actions taken since the initial complaint was made in November 2024.
Captured By:	CHARNE HAND 2025-04-03 15:29