

INSPECTOR NOTE

Building:	OPPOSITE LANDROVER NEAR A WINGERD
Street:	R44
Suburb:	
Postal Code:	
Date:	2025-02-07
Time:	16:45
Inspector:	INSPECTOR ONE

Type:	CALL RECORD - RECEIVED
Follow-Up Date:	2025-02-14
Comments:	Louis sent me the credentials of the worker on site and photos of what he fixed on site. The only remaining thing is the kennel enclosure that needs to be replaced.
Captured By:	To follow up within 7 days. INSPECTOR ONE 2025-02-07 16:45