



Inspector's Report

Case number:

209475

Address:

Athwood road, Hanover Park

Inspector:

Rudolph Philander

Stage of investigation:

Case non-completion

Date of inspection:

December 12, 2024

Time of inspection:

14:45

Comments, if any:

Follow-up moved to early next week.

Follow-up: 17 December 2024.