

INSPECTOR NOTE

Building:	
Street:	
Suburb:	DELFT SOUTH
Postal Code:	7100
Date:	2024-07-08
Time:	12:56
Inspector:	LWAZI NTUNGELE
Type:	CASE DISCUSSION NOTE
Follow-Up Date:	2024-07-09
Comments:	Area towards the informal area seemed to be blocked with water
Captured By:	LWAZI NTUNGELE 2023-06-03 12:28