

INSPECTOR NOTE

Building:	POLLSMOOR DEPARTMENT OF COREECTIONAL SERVICES
Street:	STEENBERG ROAD
Suburb:	POLLSMOOR
Postal Code:	7945
Date:	2025-03-25
Time:	19:42
Inspector:	NICOLE VENTER
Type:	EMAIL - RECEIVED
Follow-Up Date:	
Comments:	WhatsApp received from Sherwyn Loggenberg on 066 210 1875. Image proves that the broken dip bath that needs to be repaired has been reported and escalated accordingly.
Captured By:	Nicole Venter 2025-03-25 19:42